

FIG. 1A




FIG. 1B




FIG. 2A




FIG. 2B




FIG. 3A




FIG. 3B




FIG. 4A

FIG. 4B




FIG. 5A

FIG. 5B




FIG. 6

	FIRST EMBODIMENT		SECOND EMBODIMENT		THIRD EMBODIMENT	
	BEFORE ADDING RECESS PORTION	AFTER ADDING RECESS PORTION	BEFORE ADDING RECESS PORTION	AFTER ADDING RECESS PORTION	BEFORE ADDING RECESS PORTION	AFTER ADDING RECESS PORTION
APPLIED RIM	27.00/6.0		41.00/5.0		41.00/5.0	
REGULAR INTERNAL PRESSURE	700kPa		600kPa		600kPa	
REGULAR LOAD	51.5 ton		94.5 ton		94.5 ton	
WEAR INDEX	100	98	100	96	100	96
AVERAGE TEMPERATURE BETWEEN 1/4 POINTS	98°C	94°C	110°C	104°C	110°C	103°C
NEGATIVE RATE OF LAND PORTION OTHER THAN MAIN GROOVE		12.5%		20%		22%
DEPTH OF RECESS PORTION COMPARED WITH MAXIMUM DEPTH OF MAIN GROOVE		15%		40%		40%